

- Study Area (10 Rotor Diameters)
- Turbine
- Shadow Flicker Assessment Location (SFAL)
- Property Located Outside Study Area




Figure 17.1
Environmental Statement
Shadow Flicker Assessment Area

Tangy IV Wind Farm
EIA Report